



First County Scaffolding

report prepared for

ABC Construction

Scaffold Inspection Report

Report Type:

Inspection Status

Contract Number:

0001

Site Name:





York Racecourse

Site Address:

York, Station Road, United Kingdom

Date:

26th October 2017

Scaffold	Location	Area	Type	Inspection Status	Identified risks to the health and safety of any person	Hazards reported to	Inspector's recommendations	Inspector	Date & time	Next Inspection
00001	Main Retail Complex	Default area	7	Overdue	Putlogs and transoms:Some missing 3 missing on the second lift	Michael Glueck	none	John Doe 	06/10/17 14:19	13/10/17
00002		Area 2	7	Overdue	Footings:Soft and uneven Ground uneven and not stable	Michael Glueck 06/10/17	None	John Doe 	06/10/17 14:16	13/10/17
00003	Lower ground floor loc	Area 2	7	Overdue	Footings:Undermined Due to trench dug by ground works for services	Michael Glueck 06/10/17	none	John Doe 	06/10/17 14:17	13/10/17
00004	Upper void roof space	Area 2	7	Overdue	Footings:Undermined Due to trench dug by ground works for services	Michael Glueck	none	John Doe 	06/10/17 14:17	13/10/17
00005	Scaffold Location	Default area		Never inspected	-- NEVER INSPECTED --	None	None			