



# Unsafe Scaffold Report

**Site:** York Racecourse

**Customer:** ABC Construction

**Address:** York, Station Road, United Kingdom

**Scaffold:** 00001

**Area:** Default area

**Location:** Main Retail Complex

**Date:** 6th October 2017

**The above scaffold has failed the weekly inspection/spot check for the following reasons:**

**Other:** Scaffold structure damaged

Vehicle collided with the scaffold making it unsafe

## Scaffold Inspector's Recommendations

Scaffold red tagged and access blocked until remedial repairs are complete.

**Name:** John Doe

**Date:** 06/10/2017

**Signature:** JD

**Time:** 13:19

## Scaffold Supervisor's Recommendations

As above.

**Name:** John Doe

**Date:** 06/10/2017

**Signature:** JD

**Time:** 13:19

## Customer Acknowledgement Of The Unsafe Scaffold Report

**Name:** Michael Glueck

**Date:** 06/10/2017

**Signature:** MG

**Time:** 13:19

# Appendix



00001:Putlogs and transoms:Some missing  
(06/10/17 14:19)