



COMPUTER AND DESIGN SERVICES

report prepared for

EXAMPLE CUSTOMER GF

SCAFFOLD INSPECTION REPORT

All in accordance with the work at height regulations 2005 Schedule 7

Report Type:

Detailed Inspection

Site Name:

Broadstone

Site Address:

Station Approach, Broadstone BH18 8AX, United Kingdom

Date:

1st January 2000 - 7th October 2019

Table of Contents

INSPECTION SUMMARY 3

Default area: 3

DETAILED REPORT 4

Footings..... 4

Standards.....4

Ledgers.....4

Bracing..... 4

Putlogs and transoms..... 4

Couplings..... 4

Bridles.....5

Ties.....5

Boarding.....5

Guard-rails and toe-boards..... 5

Ladders.....5

fixed.....5

Cannot Inspect..... 6


Inspection Summary

Default area

 00008

 David Mincham



 07/10/19 11:23

Left terrace 8 x 4, Perimeter scaffold to plot 8

Detailed Report

Footings

- Are any of the base plates missing? 
- Is the ground suitable for the scaffold? 
- Cracked and broken footings 
- Are any of the sole boards missing? 
- Has the ground been undermined near the scaffold? 
- Other? 

Standards

- Are the standards in good working order? 
- Other? 

Ledgers

- Are any of the ledgers loose? 
- Are the ledgers level? 
- Do any joints fall in the same bay? 
- Are the ledgers in good working order? 
- Other? 

Bracing

- Are any of the plan braces missing? 
- Are any of the ledger braces missing? 
- Have all the correct fittings been used? 
- Is the bracing in good working order? 
- Other? 


Putlogs and transoms

- Are the putlogs/transoms correctly spaced? 
- Are any of the putlogs/transoms missing? 
- Are any of the putlogs/transoms loose? 
- Have all the correct fittings been used? 
- Other? 

Couplings

- Have all the correct fittings been used? 
- Are there check couplers in place? 
- Are any of the couplings loose? 
- Are any of the couplings damaged? 
- Other? 

Bridles

- Are any of the bridles incorrectly spaced? 
- Are the bridles offering enough support? 
- Have the correct couplers been used? 
- Other? 





Ties

- Have the correct number of ties been installed? 
- Are any of the ties loose? 
- Other? 

Boarding

- Are any of the boards damaged? 
- Are any of the boards causing a trip hazard? 
- Have the correct amount of boards been used? 
- Are all the boards fully supported? 
- Other? 

Guard-rails and toe-boards

- Are any of the guard rails or toe boards loose? 
- Are any of the guard rails or toe boards positioned at the wrong height? 
- Are of the guard rails or toe boards missing? 
- Other? 

Ladders

- Are all the ladders tied and secure? 
- Are all the ladders in good working order? 
- Are all the ladders sufficient in length for safe access? 
- Other? 

fixed

jhk



Cannot Inspect

Is the scaffold accessible?

